

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 2

Sewershed : Gwynn Falls

Company : URS

Date : 11/12/2008

Test to be Performed :
Smoke : X Dyed Water :

Ground Condition :
Dry : X Damp : Wet :


Supervisor : Ryan Lamont

Manhole ID : S04C_002MH






Test ID : S1032-019021

Notifications (Residents, Fire, 311) :
Yes

Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



LEGEND


-  SMOKE OBSERVATION
-  BLOWER LOCATIONS
-  MANHOLE
-  SEWER LINE
-  SMOKE RUN

Defect Code	Defect Description
SL	Service Lateral
TJ	Transition Joint
DD	Driveway Drain
WWD	Window Well Drain
STRD	Stairwell Drain
AD	Area Drain
DS	Downspout
DSC	Downspout Connection
FD	Foundation Drain

Defect Code	Defect Description
CB	Catch Basin
SD	Storm Ditch
SWMH	Storm Manhole
MAIN	Main Sewer
SANMH	Sewer Manhole
CO	Cleanout
OTHER	Other
IOB	Inside of Building

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 2 of 2
Sewershed : <u>Gwynn Falls</u>	Company : <u>URS</u>	Date : <u>11/12/2008</u>
Test to be Performed : Smoke : <u>X</u> Dyed Water : <u> </u>	Ground Condition : Dry : <u>X</u> Damp : <u> </u> Wet : <u> </u>	Supervisor : <u>Ryan Lamont</u>
Manhole ID : <u>S04C 002MH</u>	Test ID : <u>S1032-019021</u>	Notifications (Residents, Fire, 311) : <u>Yes</u>
Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)		

ID



Location: N/A; Type: Service Lateral; Smoke: Light; Status: Private Property

Defect



Landscape



Defect

